

AD-A155 649

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
CHESTNUT HILL RESERVO. (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV JAN 80

1/1


UNCLASSIFIED

F/G 13/13

NL

END

FILED



NATIONAL BUREAU OF STANDARDS
MICROCOPY RESOLUTION TEST CHART

AD-A155 649

CHARLES RIVER BASIN
BOSTON, MASSACHUSETTS

CHESTNUT HILL RESERVOIR DAM
MA 01113

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

DTIC
SELECTE
JUN 27 1985
S G D



DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

JANUARY 1980

85 06 6 035

DTIC FILE COPY

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 01113	2. GOVT ACCESSION NO. AD-A155649	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Chestnut Hill Reservoir Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE January 1980
		13. NUMBER OF PAGES 38
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Charles River Basin Boston, Massachusetts Charles River Basin		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The embankment is about 2000 ft. long with a maximum height of about 18 ft. It is intermediate in size with a high hazard potential classification. The dam is considered to be in fair condition. There are few remedial measures that the owner should undertake.		



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF
NEDED

JUN 05 1980

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:

Inclosed is a copy of the Chestnut Hill Reservoir Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition a copy of the report has also been furnished the owner, Commonwealth of Massachusetts, Metropolitan District Commission, Boston, MA 02108.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely,


MAX B. SCHEIDER

Colonel, Corps of Engineers
Division Engineer

Incl
As stated

CHESTNUT HILL RESERVOIR DAM

MA 01113

CHARLES RIVER BASIN

BOSTON, MASSACHUSETTS

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/	



PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

NATIONAL DAM INSPECTION PROGRAM

PHASE I INSPECTION REPORT

Identification No:	MA01113
Name of Dam:	Chestnut Hill Reservoir Dam
Town:	Boston
County and State:	Suffolk, Massachusetts
Stream:	Charles River Basin
Date of Inspection:	October 23, 1979

BRIEF ASSESSMENT

Chestnut Hill Reservoir Dam is an 82-year old earth embankment structure used as a reserve source of water for the City of Boston water distribution system. The embankment is approximately 2,000 feet long with a maximum height of about 18 feet and a top width of 20 feet. The riprapped upstream face of the dam is on a slope of 1.5H:1V and the grass covered downstream face is on a slope of 2H:1V. Effluent Gatehouse No.1, near the north abutment, is a cut stone masonry structure about 40 feet by 50 feet in plan and Effluent Gatehouse No.2, near the south abutment, is a cut stone masonry structure about 16 feet by 28 feet in plan.

The normal pool surface area is 73 acres which is also the drainage area because the reservoir is not located on a stream. The maximum storage to the top of the dam is 1,270 acre-feet which places the structure in the "Intermediate" size classification. A breach of the dam would affect a municipal park, a business district and an urban residential neighborhood; therefore, the dam has been classified as having a "High" hazard potential. Based on the "Intermediate" size and "High" hazard potential, the test flood is the full Probable Maximum Flood (PMF). Since no inflow from the drainage area runoff occurs at Chestnut Hill Reservoir, the full Probable Maximum Precipitation(PMP) is considered the test flood and is applied directly to the normal pool surface area.


The dam is considered to be in fair condition. Saplings have been recently planted on the downstream face, it is not known if the gates and gate valves in Effluent Gatehouses 1 and 2 are operable, many animal burrows were observed on the downstream face and the catch basin system at the downstream toe of the embankment appears to be completely plugged.

The test flood for the facility is 22.9 inches of rainfall falling directly on the reservoir. Since the reservoir surface level is constantly maintained as close as possible to the normal level, which is 4 feet below the top of the dam, chances of the embankment being overtopped during the test flood event are extremely remote.

Within one year after receipt of this Phase I Inspection report, the Owner, the Metropolitan District Commission (MDC), should engage a qualified registered professional engineer to: 1) investigate the seismic stability of the dam; 2) supervise the removal of the saplings from the downstream face of the dam; and 3) determine the source of the water on the floor of Effluent Gatehouse No.1.

The MDC should implement the following operation and maintenance procedures: 1) check the operability of the gates and gate valves in Effluent Gatehouses 1 and 2 and, if necessary, repair them; 2) clean out and repair the catch basin system along the downstream toe of the dam; 3) backfill all animal burrows; 4) institute a program of annual periodic technical inspection; 5) develop and adhere to a comprehensive maintenance program; and 6) develop a formal surveillance and flood warning plan.

O'BRIEN & GERE ENGINEERS, INC.



Date 30 April 1980

This Phase I Inspection Report on Chestnut Hill Reservoir Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Carney M. Terzian

CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division

Richard J. DiBuono

RICHARD DIBUONO, MEMBER
Water Control Branch
Engineering Division

Aramast Mahtesian

ARAMAST MAHTESIAN, CHAIRMAN
Geotechnical Engineering Branch
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar
JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation: however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi

REPORT

I. PROJECT INFORMATION	1-1
1.1 General	1-1
a. Authority	1-1
b. Purpose of Inspection	1-1
1.2 Description of Project	1-1
a. Location	1-1
b. Description of Dam and Appurtenances	1-2
c. Size Classification	1-2
d. Hazard Classification	1-2
e. Ownership	1-3
f. Operator	1-3
g. Purpose of Dam	1-3
h. Design and Construction History	1-3
i. Normal Operating Procedure	1-3
1.3 Pertinent Data	1-3
a. Drainage Area	1-3
b. Discharge at Damsite	1-3
c. Elevation	1-4
d. Reservoir	1-4
e. Storage	1-4
f. Reservoir Surface	1-4
g. Dam	1-5
h. Diversion and Regulating Tunnel	1-5
i. Spillway	1-5
j. Regulating Outlets	1-5

TABLE OF CONTENTS (Con't)


<u>SECTION</u>	<u>PAGE</u>
2. ENGINEERING DATA	
2.1 Design Data	2-1
2.2 Construction Data	2-1
2.3 Operation Data	2-1
2.4 Evaluation of Data	2-1
a. Availability	2-1
b. Adequacy	2-1
c. Validity	2-1
3. VISUAL INSPECTION	
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-1
d. Reservoir Area	3-2
e. Downstream Channel	3-2
3.2 Evaluation	3-2
4. OPERATIONAL AND MAINTENANCE PROCEDURES	
4.1 Operational Procedures	4-1
a. General	4-1
b. Description of Any Warning System in Effect	4-1
4.2 Maintenance Procedures	4-1
a. General	4-1
b. Operating Facilities	4-1
4.3 Evaluation	4-1
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	
5.1 General	5-1
5.2 Design Data	5-1
5.3 Experience Data	5-1
5.4 Test Flood Analysis	5-1
5.5 Dam Failure Analysis	5-1

TABLE OF CONTENTS (Con't)

<u>SECTION</u>	<u>PAGE</u>
6. EVALUATION OF STRUCTURAL STABILITY	
6.1 Visual Observation	6-1
6.2 Design and Construction Data	6-1
6.3 Post-Construction Data	6-1
6.4 Seismic Stability	6-1
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-1
a. Operation and Maintenance Procedures	7-1
7.4 Alternatives	7-2

APPENDICES


APPENDIX A - INSPECTION CHECKLIST	A-1 to A-7
APPENDIX B - ENGINEERING DATA	B-1 to B-2
APPENDIX C - PHOTOGRAPHS	C-1 to C-5
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1 to D-6
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	



OVERVIEW OF THE CHESTNUT HILL RESERVOIR DAM FROM THE NORTHERN
ABUTMENT WITH EFFLUENT GATEHOUSE NO. 1 IN THE BACKGROUND.
(10/23/79)



OVERVIEW OF THE CHESTNUT HILL RESERVOIR DAM FROM THE WESTERN
ABUTMENT WITH THE EFFLUENT GATEHOUSE NO. 2 IN THE BACKGROUND.
(10/23/79)



NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT
CHESTNUT HILL RESERVOIR DAM

SECTION 1

PROJECT INFORMATION

1.1 General

a. Authority. The National Dam Inspection Act of August 8, 1972 (Public Law 92-367), authorized the Secretary of the Army, through the Corps of Engineers, to initiate the National Program for Inspection of Dams throughout the United States. Responsibility for supervising inspection of dams in the New England Region has been assigned to the New England Division of the Corps of Engineers.

O'Brien & Gere Engineers, Inc. has been retained by the New England Division to inspect and report on selected non-federal dams in the Commonwealth of Massachusetts. Authorization and Notice to Proceed were issued to O'Brien & Gere by a letter dated November 6, 1979 and signed by Colonel William E. Hodgson, Jr. Contract No. DACW33-80-C-0014 has been assigned by the Corps of Engineers for this work.

b. Purpose of Inspection. The purpose of inspecting and evaluating non-federal dams is to:

1. Identify conditions which threaten public safety and make the Owner aware of any deficiencies so that he may correct them in a timely manner.

2. Encourage and prepare the states to initiate effective dam safety programs for non-federal dams as soon as possible.

3. Update, verify and complete the National Inventory of Dams.

1.2 Description of Project (Information obtained from the Commonwealth of Massachusetts, Metropolitan District Commission (MDC)).

a. Location. Chestnut Hill Reservoir, which is not on a stream, is located adjacent to the Boston College campus along the western boundary of the City of Boston, Suffolk County, Massachusetts. The site is shown on the "Newton, Massachusetts" USGS Quadrangle at coordinates N 42°20.1', W 71° 9.3'. A regional location of Chestnut Hill Reservoir Dam is included as Figure 1, Page vi.

A municipal park, a business district and a residential neighborhood are located within the potential flood impact area beginning within a few hundred feet east of the dam.

b. Description of Dam and Appurtenances. Chestnut Hill Reservoir Dam is an earth embankment approximately 2,000 feet long with a maximum height of about 18 feet and a top width of 20 feet. The riprapped upstream face of the dam is on a slope of 1.5H:1V and the downstream face is grass covered on a slope of 2H:1V. The downstream face in the vicinity of Effluent Gatehouse No. 1 is provided with a 13-foot wide berm at the mid-height of the embankment. The berm, which is about 180 feet long, is symmetrical about the Effluent Gatehouse No.1 centerline and tapers into the prevailing embankment slope at each end.

Effluent Gatehouse No.1, near the north abutment, is a cut stone masonry structure about 40 feet by 50 feet in plan and is located at the crest of the upstream face of the dam. The structure contains four inlet portals of unknown dimensions which are provided with stoplog slots. Discharge from the intake chamber to the two 48-inch diameter cast iron water supply conduits is controlled by 2 four-foot square sluice gates. Downstream of the sluice gates are five 48-inch diameter manually operated non-rising stem gate valves located in a chamber within the embankment. Each of the two water supply conduits is equipped with two gate valves in series and the fifth valve is used to control flow in a 48-inch diameter cross-connecting conduit. This gatehouse has not been used for several years. Refer to pages B-1 and B-2.

Effluent Gatehouse No. 2, near the south abutment, is a cut stone masonry structure about 16 feet by 28 feet in plan constructed at the crest of the upstream face of the dam. The structure contains three inlet portals of unknown dimensions which are provided with screens and stoplog slots. Discharge from the intake chambers to the three 60-inch diameter connecting conduits is controlled by three manually operated gate valves. Pages B-1 and B-2 show the complex interconnections of these pipes with the MDC water supply system. This gatehouse has not been used for several years.

The Intermediate Gatehouse on the west side of the reservoir is a cut stone masonry structure which houses a 5-foot square gate used to maintain the impoundment level in Chestnut Hill Reservoir at Elevation 128.3 by allowing discharge to flow into an abandoned section of the Cochituate Aqueduct.

Chestnut Hill Reservoir Dam does not have a spillway.

c. Size Classification. The maximum storage capacity of 1,270 acre-feet, which is more than 1,000 acre-feet and less than 50,000 acre-feet, places Chestnut Hill Reservoir Dam in the "Intermediate" size category.

d. Hazard Classification. Chestnut Hill Reservoir is located within the City of Boston corporate boundary. Beacon Street, a major thoroughfare, parallels the downstream toe of the dam for nearly the entire length of the embankment. Two major pumping stations operated by the Metropolitan District Commission are located 200 feet southeast of the embankment. A municipal park, a business district and an urban residential neighborhood are located within the potential flood impact area beginning a few hundred feet east of the dam. The failure analysis indicates that the assumed breach of the dam would result in a 9.2 foot depth of water in the flood impact area. As a result, there would be at least 6 feet of water in the first floors of most of the buildings in the flood impact area.

Since flood waters resulting from a failure of Chestnut Hill Reservoir Dam would cause excessive property damage and the possible loss of more than a few lives, the dam is classified as "High" hazard.

e. Ownership. The dam is owned by the Commonwealth of Massachusetts, Metropolitan District Commission (MDC), 20 Somerset Street, Boston, Massachusetts 02108, Telephone (617) 727-5275.

f. Operator. The dam is operated by the MDC, Water Division. Mr. William R. Thompson, Superintendent, is in charge of dam operations. His address is 20 Somerset Street, Boston, Massachusetts 02108, Telephone (617) 396-4631.

g. Purpose of Dam. The dam was built to impound a water distribution reservoir. The reservoir has not been used on a regular basis since 1973 and is currently used as a reserve source of water supply only.

h. Design and Construction History. The construction of Chestnut Hill Reservoir (originally known as Bradlee Basin) Dam was completed in 1898. Further information is not available.

i. Normal Operating Procedures. According to the Owner's representative, Mr. Thompson, since 1973 the only operation relative to the Chestnut Hill Reservoir is the provision for discharge through a 5-foot square gate in the Intermediate Gatehouse (on the west side of Chestnut Hill Reservoir) into an abandoned section of the Conchituate Aqueduct to maintain the Chestnut Hill Reservoir level at Elevation 128.3. Elevation 128.3 is 4 feet below the top of the dam.

If it is necessary to use Chestnut Hill Reservoir, water would be supplied from the Sudbury Reservoir (about 20 miles west of Chestnut Hill Reservoir). Gates would be opened at Sudbury Reservoir and 16 hours later the discharge would reach Chestnut Hill Reservoir. No inlet controls are available at Chestnut Hill Reservoir. Both the high service and low service pumping stations, across Beacon Street from Chestnut Hill Reservoir, would be put into operation if Chestnut Hill Reservoir is restored to service.

1.3 Pertinent Data

a. Drainage Area. The area draining to Chestnut Hill Reservoir is equal to the reservoir surface area of 0.11 square miles.

b. Discharge at Damsite.

1. Outlet Works. As discussed in Section 1.2.i, since 1973 the only outlet functioning is the 5-foot square gate in the Intermediate Gatehouse, used to maintain the impoundment level in Chestnut Hill Reservoir at Elevation 128.3 by allowing discharge to flow into an abandoned section of the Cochituate Aqueduct. According to the Owner's representative, it is not known if the gates and gate valves in Effluent Gatehouses 1 and 2 are operable. If operable, they could be used to drawdown the entire impoundment.

2. Maximum Known Flood. Not applicable.
3. Ungated Spillway Capacity at Top of Dam. Not applicable.
4. Ungated Spillway Capacity at Test Flood Elevation. Not applicable.
5. Gated Spillway Capacity at Normal Pool. Not applicable.
6. Gated Spillway Capacity at Test Flood Elevation. Not applicable.
7. Total Project Discharge at Top of Dam. Not applicable.
8. Total Project Discharge at Test Flood Elevation. Not applicable.

c. Elevation. (NGVD)

- | | |
|---------------------------------------|--------------------|
| 1. Streambed at Toe of Dam | 114.3 ⁺ |
| 2. Bottom of Cutoff | Unknown |
| 3. Maximum Tailwater | NA |
| 4. Normal Pool | 128.3 |
| 5. Full Flood Control Pool | NA |
| 6. Spillway Crest | NA |
| 7. Design Surcharge (Original Design) | Unknown |
| 8. Top of Dam | 132.3 |
| 9. Test Flood Surcharge | 130.2 |

d. Reservoir Length. (feet)

- | | |
|------------------------|--------------------|
| 1. Normal Pool | 2,300 ⁺ |
| 2. Flood Control Pool | NA |
| 3. Spillway Crest Pool | NA |
| 4. Top of Dam | 2,300 ⁺ |
| 5. Test Flood Pool | 2,300 ⁺ |

e. Storage. (Acre-Feet)

- | | |
|------------------------|-------|
| 1. Normal Pool | 970 |
| 2. Flood Control Pool | NA |
| 3. Spillway Crest Pool | NA |
| 4. Top of Dam | 1,270 |
| 5. Test Flood Pool | 1,120 |

f. Reservoir Surface. (Acres)

- | | |
|------------------------|----|
| 1. Normal Pool | 73 |
| 2. Flood Control Pool | NA |
| 3. Spillway Crest Pool | NA |
| 4. Top of Dam | 73 |
| 5. Test Flood Pool | 73 |

g. Dam.

1. Type	Earth Embankment
2. Length	2,000 feet
3. Height	18 feet
4. Top Width	20 feet
5. Side Slopes (upstream)	1.5H:1V
(downstream)	2.0H:1V
6. Zoning	Unknown
7. Impervious Core	Unknown
8. Cutoff	Unknown
9. Grout Curtain	Unknown

h. Diversion and Regulating Tunnel. Not Applicable

i. Spillway. Not Applicable

j. Regulating Outlets.

1. Effluent Gatehouse No.1

a. Invert Elevation	Unknown
b. Size	Two 48-inch diameter pipes
c. Description	Two 48-inch diameter gate valves on each 48-inch diameter pipe plus a 48-inch diameter gate valve on a 48-inch cross connecting pipe.
d. Control Mechanism	Hand Wheels
e. Other	According to the Owner's representative, it is not known if the gate valves are operable.

2. Effluent Gatehouse No.2

a. Invert	Unknown
b. Size	Three 60-inch diameter pipes
c. Description	60-inch diameter gate valve on each of the three 60-inch diameter pipes.
d. Control Mechanism	Hand Wheels
e. Other	According to the Owner's representative, it is not known if the gate valves are operable.

SECTION 2

ENGINEERING DATA

2.1 Design

Drawings with limited information were made available for review of the Chestnut Hill Reservoir Dam. Reductions of the drawings are in Appendix B of this report. No design calculations are available for this site.

2.2 Construction

No information is available concerning the construction of Chestnut Hill Reservoir Dam.

2.3 Operation

The MDC, Water Division, maintains daily readings of reservoir pool elevations.

2.4 Evaluation

a. Availability. The information made available was obtained from the Commonwealth of Massachusetts, Metropolitan District Commission (MDC).

b. Adequacy. The drawings, visual inspection data and conversations with the Owner's representative are considered to be adequate for a Phase I investigation.

c. Validity. The data made available for this site investigation appears to be valid.

SECTION 3

VISUAL INSPECTION

3.1 Findings

a. General. The field inspection of Chestnut Hill Reservoir Dam was performed on October 23, 1979. At the time of the inspection, the reservoir water surface was approximately 4.0 feet below the top of the dam. No underwater areas were inspected. The observations and comments of the field inspection team are in the checklist which is Appendix A of this report.

b. Dam. The dam appears to be in fair condition. The upstream face of the embankment is protected with large dumped riprap which extends to within two feet of the dam crest and is capped with 6-inch thick cut stone blocks. There is no evidence of displacement of the riprap. The crest of the dam is grass covered except for a 5-foot wide gravel walkway. The crest is constructed with a 2-foot differential between the upstream and downstream faces of the dam to provide drainage into the reservoir. The downstream face of the dam has a uniform slope of 2H:1V and is grass covered. About two dozen saplings have been planted in a random fashion on the downstream face between the gatehouses (refer to page C-2). The berm on the downstream face near Effluent Gatehouse No. 1 appears to have been constructed to accommodate a landing in the concrete steps leading from the downstream toe to the crest of the dam (refer to page C-1). No seepage was observed at the downstream toe or on the downstream face of the dam. Several rodent holes were observed on the downstream face at scattered locations (refer to page C-4). Four grated catch basins were observed at variable spacing along the downstream embankment toe. The basins were clogged with debris and were dry at the time of the inspection.

c. Appurtenant Structures. Effluent Gatehouse No. 1 has no indications of settlement or misalignments. Access to the valve chamber is through doors at the downstream toe of the dam. The wooden platform in the chamber is about five feet above the pipe invert and is severely deteriorated. The stairs leading to the gatehouse floor at the dam crest elevation were considered unsafe; therefore, the interior of the gatehouse at this elevation was not inspected. The operating wheels for the five 48-inch diameter gate valves were in place; however, according to the Owner's representative, three feet of standing water was noted on the floor of the chamber. The brick walls were wet but there was no evidence of a concentrated discharge into the chamber. No lighting fixtures were noted within the gate chamber.

Effluent Gatehouse No. 2 has no indications of settlement or misalignments. The gate valve operators within the gatehouse are enclosed (refer to page C-5). According to the Owner's representative, it is not known if the gate valves are operable. A reservoir stage recorder, consisting of a float and a graduated rod, is located within the gatehouse. The mechanical gate hoist and supporting beam for installation and removal of stoplogs appear to be in operating condition.

The Intermediate Gatehouse has no indications of settlement or misalignment. Within this gatehouse is the 5-foot square gate used to maintain the impoundment level in Chestnut Hill Reservoir at Elevation 128.3. The gate is operational.

d. Reservoir Area. The entire perimeter of the reservoir consists of MDC property which is primarily well maintained lawns and some wooded areas along the north and northeast sides of the reservoir. No indications of shoreline instability or excessive siltation were observed during the inspection.

e. Downstream Channel. Chestnut Hill Reservoir is not located on a stream and a spillway has not been incorporated into the structure. The local topography is such that flood waters would be directed to the east along Beacon Street, through Cleveland Circle and into the Muddy River approximately two miles to the east.

3.2 Evaluation. The dam and appurtenances appear to be in fair condition. Saplings have recently been planted on the downstream face and many animal burrows were observed in the downstream face. Three feet of standing water was observed on the floor of Effluent Gatehouse No. 1. It is not known if the gates and the gate valves in Effluent Gatehouses 1 and 2 are operable. The catch basin system at the downstream toe of the embankment appears to be completely plugged.

SECTION 4

OPERATIONAL AND MAINTENANCE PROCEDURES

4.1 Operational Procedures

a. General. According to Mr. Thompson, the reservoir is used only as a reserve source of water. Since 1973, the only outlet functioning is the 5-foot square gate in the Intermediate Gatehouse which is used to maintain the impoundment level at Elevation 128.3 by allowing discharge to flow into an abandoned section of the Cochituate Aqueduct.

b. Description of Any Warning System in Effect. According to Mr. Thompson, no flood warning system is in effect at this site.

4.2 Maintenance Procedures

a. General. According to Mr. Thompson, the grass on the embankment is cut twice a year.

b. Operating Facilities. According to Mr. Thompson, it is not known if the gates and gate valves in both gatehouses, which have not been used since 1973, are operable. The 5-foot square gate in the Intermediate Gatehouse is regularly maintained to insure that it can be used to hold the water level in the impoundment to Elevation 128.3.

4.3 Evaluation

The operational procedures of the outlet works, as described by Mr. Thompson, are considered to be satisfactory for the gate used in the Intermediate Gatehouse, but unsatisfactory for gates and gate valves in Effluent Gatehouses 1 and 2.

SECTION 5

EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

5.1 General.

Chestnut Hill Reservoir Dam is not located on a stream. Therefore, its drainage area is limited to the reservoir area.

5.2 Design Data

No hydraulic or hydrologic information is available relative to the original design.

5.3 Experience Data

No notable hydrologic events have occurred at this site. According to the Owner's representative, the embankment has never been overtopped.

5.4 Test Flood Analysis

Based on the "Intermediate" size and "High" hazard potential, the test flood is the full Probable Maximum Flood (PMF). Since no inflow from drainage area runoff occurs at Chestnut Hill Reservoir, the full Probable Maximum Precipitation (PMP) is considered the test flood and is applied directly to the normal pool surface area.

The PMP, if totally stored, would raise the reservoir pool level 22.9 inches (refer to Appendix D) above the normal pool and result in an estimated 2.10 feet of freeboard. Since the reservoir surface level is constantly maintained as close as possible to normal pool Elevation 128.3, chances of the embankment being overtopped during the PMP event are extremely remote.

5.5 Dam Failure Analysis

The dam failure analysis was performed using the HEC-1-DB computer program. The breach was performed with the reservoir at the PMP elevation of 130.2. The failure was assumed to progress to full breach width of about 200 feet in 2 hours. The assumed failure would be a result of piping of the embankment since the embankment would not be overtopped.

The downstream hazard area east of the reservoir is an urban neighborhood which contains very closely spaced multi-family dwellings and commercial establishments. Flood waters from the breach would probably be directed through this area along Beacon Street and into the Muddy River approximately 2 miles to the east. The potential flood impact area was taken at a natural constriction in the topography about 1,300 feet east of the dam. Due to the prevalence of man-made structures in the path of the flood, the Manning's roughness coefficient for the channel (Beacon Street) and overbanks was chosen to be 0.10 to reflect the considerable energy losses from buildings, automobiles and other obstructions.

Results of the breach of Chestnut Hill Reservoir Dam indicate that the maximum flood discharge at the impact area would be 11,530 cfs with a corresponding depth of 9.2 feet. As a result, there would be at least 6 feet of water in the first floor of most of the buildings in the flood impact area. Such a flood would cause excessive property damage and the possible loss of more than a few lives.

SECTION 6

EVALUATION OF STRUCTURAL STABILITY

6.1 Visual Observations

At the time of the inspection, there were no indications of distortions or undulations of the embankment crest or slopes. The roots of trees on the downstream slope have a deleterious effect upon the compacted materials within the embankment and may provide seepage paths through the dam. The rodent holes may also increase the seepage potential which could lead to piping failure of the dam.

6.2 Design and Construction Data

The dam appears to have been constructed in general conformance with the record drawings shown on page B-1 and B-2.

6.3 Post-Construction Changes

No post-construction changes have been recorded at this site.

6.4 Seismic Stability

Chestnut Hill Reservoir Dam is located in Seismic Zone 3 on the "Seismic Zone Map of Contiguous States". Therefore, according to the recommended guidelines for Phase I Safety Inspection of Dams, a seismic stability analysis should be performed as recommended in Section 7.

SECTION 7

ASSESSMENT, RECOMMENDATIONS & REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. The dam and appurtenances appear to be in fair condition. The tree roots and rodent burrows in the downstream face of the dam may lead to the development of seepage paths through the embankment. The 3 feet of water on the floor of Effluent Gatehouse No. 1 could be indicative of a seepage problem. In case of an emergency, it is not known if the reservoir could be drawn down because of the uncertain condition of the gates and gate valves in Effluent Gatehouses 1 and 2. The catch basin system at the downstream toe of the embankment appears to be completely plugged.

b. Adequacy of Information. The drawings, visual inspection data and conversations with the Owner's representative are considered adequate for a Phase I assessment of the Chestnut Hill Reservoir Dam.

c. Urgency. The recommendations and remedial measures described in Sections 7.2 and 7.3 of this report should be implemented within one year of receipt of this Phase I Inspection Report.

7.2 Recommendations

The Owner, the MDC, should engage a qualified registered professional engineer to:

1. Investigate the seismic stability of the dam.
2. Supervise the removal of trees from the downstream face of the dam.
3. Determine the source of the water on the floor of Effluent Gatehouse No. 1.

7.3 Remedial Measures

a. Operational and Maintenance Procedures. The MDC should implement the following operational and maintenance measures:

1. Check the operability of the gates and gate valves in Effluent Gatehouses 1 and 2 and, if necessary, repair them.
2. Clean out and repair the catch basin system along the downstream toe of the dam.
3. Backfill all animal burrows.

4. Institute a program of annual periodic technical inspection.
5. Develop and adhere to a comprehensive maintenance program.
6. Develop a formal surveillance and flood warning plan.

7.4 Alternatives

No valid alternatives to the recommendations described above are considered feasible for this site.

APPENDIX A

INSPECTION CHECKLIST

VISUAL INSPECTION CHECK LIST

INSPECTION TEAM ORGANIZATION

Project: CHESTNUT HILL RESERVOIR DAM

National I.D. #: MA 1113

Location: Boston, MA.

Type of Dam: Earth Embankment

Inspection Date(s): October 23, 1979

Weather: Clear, 64°

Pool Elevation: 134.0 MSL

Inspection Team

Leonard Beck
Steven Snider
Alan Hanscom
Rodney Georges

O'Brien & Gere
O'Brien & Gere
O'Brien & Gere
Bryant & Associates

Structures
Foundations & Materials
Structures
Hydrology/Hydraulics

*Mr. John J. Williams, Vice-President, O'Brien & Gere has visited the site but not necessarily in conjunction with the inspection team.

Owner's Representative

Mr. William R. Thompson, Superintendant, Water
Division, Metropolitan District Commission

VISUAL INSPECTION CHECK LIST

Project: CHESTNUT HILL RESERVOIR DAM

National I.D. #: MA 1113

Date(s): October 23, 1979

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT</u>	
Crest Elevation	138.0MSL
Current Pool Elevation	134.0MSL
Maximum Impoundment to Date	Unknown.
Surface Cracks	None.
Pavement Condition	N/A
Movement or Settlement of Crest	None.
Lateral Movement	None.
Vertical Alignment	Good.
Horizontal Alignment	Good.
Condition at Abutment and at Concrete Structures	No problems noted.
Indications of Movements of Structural Items on Slopes	None.
Trespassing on Slopes	None.
Vegetation on Slopes	Deciduous saplings on d/s slope.
Sloughing or Erosion of Slopes or Abutments	Rodent burrows on d/s slope.
Rock Slope Protection - Riprap Failures	None.

VISUAL INSPECTION CHECK LIST

Project: CHESTNUT HILL RESERVOIR DAM

National I.D. #: MA 1113

Date(s): October 23, 1979

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT (Con't)</u>	
Unusual Movement or Cracking at or near Toes	<i>None.</i>
Unusual Embankment or Downstream Seepage	<i>None.</i>
Piping or Boils	<i>None.</i>
Foundation Drainage Features	<i>Unknown.</i>
Toe Drains	<i>None.</i>
Instrumentation System	<i>None.</i>

VISUAL INSPECTION CHECK LIST

Project: CHESTNUT HILL RESERVOIR DAM

National I.D. #: MA 1113

Date(s): October 23, 1979

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - CONTROL TOWER</u>	<u>EFFLUENT GATEHOUSE NO. 1</u>
a. Concrete and Structural	
General Condition	Good.
Condition of Joints	Good.
Spalling	Slight loss of mortar.
Visible Reinforcing	None.
Rusting or Staining of Concrete	None.
Any Seepage or Efflorescence	Moist walls in gate chamber
Joint Alignment	Good.
Unusual Seepage or Leaks in Gate Chamber	None, but 3 feet of water on floor of gate chamber.
Cracks	None.
Rusting or Corrosion of Steel	None.
b. Mechanical and Electrical	
Air Vents	None.
Float Wells	None.
Crane Hoist	None.

VISUAL INSPECTION CHECK LIST

Project: CHESTNUT HILL RESERVOIR DAM

National I.D. #: MA 1113

Date(s): October 23, 1979

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - CONTROL TOWER (Con't)</u>	
Elevator	N/A
Hydraulic System	N/A
Service Gates	All 48" ϕ gates are operable.
Emergency Gates	N/A
Lighting Protection System	None.
Emergency Power System	N/A
Wiring and Lighting System in Gate Chamber	N/A
A-5	

VISUAL INSPECTION CHECK LIST

Project: CHESTNUT HILL RESERVOIR DAM

National I.D. #: MA 1113

Date(s): October 23, 1979

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - CONTROL TOWER</u>	<u>EFFLUENT GATEHOUSE NO. 2</u>
a. Concrete and Structural	
General Condition	Good.
Condition of Joints	Good.
Spalling	None.
Visible Reinforcing	None.
Rusting or Staining of Concrete	None. Stone masonry structure.
Any Seepage or Efflorescence	None.
Joint Alignment	Good.
Unusual Seepage or Leaks in Gate Chamber	None noted.
Cracks	None.
Rusting or Corrosion of Steel	Some corrosion of stop log hoist & support beam.
b. Mechanical and Electrical	
Air Vents	N/A
Float Wells	Stage recorder consisting of grad. rod and float.
Crane Hoist	Operable.

VISUAL INSPECTION CHECK LIST

Project: CHESTNUT HILL RESERVOIR DAM

National I.D. #: N/A 1113

Date(s): October 23, 1979


AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - CONTROL TOWER (Con't)</u>	
Elevator	N/A
Hydraulic System	N/A
Service Gates	All 3- 60.5" ϕ gates are operable.
Emergency Gates	No stop logs at site.
Lighting Protection System	N/A
Emergency Power System	N/A
Wiring and Lighting System in Gate Chamber	N/A

APPENDIX B

ENGINEERING DATA


APPENDIX B
ENGINEERING DATA
TABLE OF CONTENTS

	<u>PAGE</u>
PLAN OF GATES	B-1
RESERVOIR & GROUNDS, GENERAL PLAN	B-2



DATE	NO	GATE	TIME
10/10/1918	1	1st Gate	5:00 AM
10/10/1918	2	2nd Gate	5:00 AM
10/10/1918	3	3rd Gate	5:00 AM
10/10/1918	4	4th Gate	5:00 AM
10/10/1918	5	5th Gate	5:00 AM
10/10/1918	6	6th Gate	5:00 AM
10/10/1918	7	7th Gate	5:00 AM
10/10/1918	8	8th Gate	5:00 AM
10/10/1918	9	9th Gate	5:00 AM
10/10/1918	10	10th Gate	5:00 AM

SUPPLEMENTARY TABLE			MARCH 1900	
LUTATION	WIND	GATE	SIZE	
Small (100 ft)	10	28 - 30	28	50 in
100 ft	10	Hydraulic Gates	60	5
100 ft	10	28 - 30	12	
100 ft	10	28 - 30	36	



APPENDIX C

PHOTOGRAPHS

APPENDIX C
SELECTED PHOTOGRAPHS OF PROJECT

LOCATION PLAN

Site Plan Sketch

Page
No.

A

PHOTOGRAPHS

No.

Page
No.

- | | | |
|-----|--|---|
| 1. | Downstream approach to effluent gatehouse No. 1 showing the potential hazard area in the background. | 1 |
| 2. | Effluent gatehouse No. 1 as viewed from downstream. | 1 |
| 3. | Downstream slope of the dam showing the berm and recently planted saplings looking north. | 2 |
| 4. | Downstream slope of the dam looking southwest showing the recently planted saplings on the embankment. | 2 |
| 5. | Effluent gatehouse No. 2 looking towards the western abutment. | 3 |
| 6. | Southeastern dam crest showing buildings and street of the potential hazard area in the background. | 3 |
| 7. | Chestnut Hill Reservoir showing Boston College in the western background. | 4 |
| 8. | Typical rodent hole in the downstream face of the dam. | 4 |
| 9. | Gate stems and hoists inside the effluent gatehouse No. 1. | 5 |
| 10. | Housing for the gate hoists inside the effluent gatehouse No. 2. | 5 |

U.S. ARMY CORPS OF ENGINEERS

NEW ENGLAND DIVISION

Contract No. DACW 33-80-C-0014

CHESTNUT HILL RESERVOIR DAM

SITE PLAN


O'BRIEN & GERE

DATE: JANUARY 1980

SCALE: NONE

A

452



PAGE A

COMMONWEALTH OF MASSACHUSETTS
METROPOLITAN WATER WORKS
SUDBURY DEPT.

PLAN OF GATES

CHESTNUT HILL RESERVOIR

1 inch = 100 feet

Scale 1 inch = 100 feet

Copy available to DTIC does not
permit fully legible reproduction.


TABLE OF GATES

LOCATION	NAME	SIZE
1	Gate 1	48" x 48"
2	Gate 2	48" x 48"
3	Gate 3	48" x 48"
4	Gate 4	48" x 48"
5	Gate 5	48" x 48"
6	Gate 6	48" x 48"
7	Gate 7	48" x 48"
8	Gate 8	48" x 48"
9	Gate 9	48" x 48"
10	Gate 10	48" x 48"
11	Gate 11	48" x 48"
12	Gate 12	48" x 48"
13	Gate 13	48" x 48"
14	Gate 14	48" x 48"
15	Gate 15	48" x 48"
16	Gate 16	48" x 48"
17	Gate 17	48" x 48"
18	Gate 18	48" x 48"
19	Gate 19	48" x 48"
20	Gate 20	48" x 48"

LOCATION	NAME	SIZE
1	Gate 1	48" x 48"
2	Gate 2	48" x 48"
3	Gate 3	48" x 48"
4	Gate 4	48" x 48"
5	Gate 5	48" x 48"
6	Gate 6	48" x 48"
7	Gate 7	48" x 48"
8	Gate 8	48" x 48"
9	Gate 9	48" x 48"
10	Gate 10	48" x 48"
11	Gate 11	48" x 48"
12	Gate 12	48" x 48"
13	Gate 13	48" x 48"
14	Gate 14	48" x 48"
15	Gate 15	48" x 48"
16	Gate 16	48" x 48"
17	Gate 17	48" x 48"
18	Gate 18	48" x 48"
19	Gate 19	48" x 48"
20	Gate 20	48" x 48"




1. DOWNSTREAM APPROACH TO THE EFFLUENT GATEHOUSE NO. 1 SHOWING THE POTENTIAL HAZARD AREA IN THE BACKGROUND. (10/23/79)



2. EFFLUENT GATEHOUSE NO. 1 AS VIEWED FROM DOWNSTREAM. (10/23/79)




3. DOWNSTREAM SLOPE OF THE DAM SHOWING THE BERM AND RECENTLY PLANTED SAPLINGS LOOKING NORTH. (10/23/79)




4. DOWNSTREAM SLOPE OF THE DAM LOOKING SOUTHWEST SHOWING THE RECENTLY PLANTED SAPLINGS ON THE EMBANKMENT. (10/23/79)



5. EFFLUENT GATEHOUSE NO. 2 LOOKING TOWARDS THE WESTERN ABUTMENT.
(10/23/79)




6. SOUTHEASTERN DAM CREST SHOWING BUILDINGS AND STREET OF THE
POTENTIAL HAZARD AREA IN THE BACKGROUND. (10/23/79)



7. CHESTNUT HILL RESERVOIR SHOWING BOSTON COLLEGE IN THE WESTERN BACKGROUND. (10/23/79)



8. TYPICAL RODENT HOLE IN THE DOWNSTREAM FACE OF THE DAM. (10/23/79)



9. GATE STEMS AND HOISTS INSIDE EFFLUENT GATEHOUSE NO. 1.(10/23/79)



10. HOUSING FOR THE GATE
HOISTS INSIDE EFFLUENT
GATEHOUSE NO. 2. (10/23/79)

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS


SUBJECT	SHEET	BY	DATE	JOB NO
<i>CHESTNUT HILL RESERVOIR DAM</i>				

APPENDIX D

HYDROLOGIC & HYDRAULIC COMPUTATIONS

TABLE OF CONTENTS

	<u>PAGE</u>
<i>REGIONAL VICINITY MAP, FIGURE 1, SHOWING FLOOD IMPACT AREA</i>	<i>D-1</i>
<i>STAGE-AREA, STAGE-STORAGE, & HAZARD AREA INFORMATION</i>	<i>D-2</i>
<i>HEC-1 DAM SAFETY VERSION, BREACH ANALYSIS, COMPUTER OUTPUT</i>	<i>D-3</i>
	<i>thru D-6</i>



JOB NED-COE, CHESTNUT HILL RES. DAM

SHEET NO D-2 OF _____

CALCULATED BY RG DATE

CHECKED BY SHS DATE

SCALE _____

CHESTNUT HILL RESERVOIR DAM - H&H

PMP CALCS. (TEST FLOOD):

FROM HMS # 33 → 24 HR., 200 SQ. MI. INDEX RAINFALL = 21.5 INCHES

INDEX % FOR < 10 SQ. MI. AREA (FOR 24 HR. STORM) = 133%; HOP BROOK
FACTOR (FOR PROBABILITY OF IMPERFECT FIT OF STORM OVER BASIN) = 0.8.

TEST FLOOD \rightarrow 24 HR. PMP = $(1.33)(0.8)(21.5) = 22.9$ INCHES


APPLYING THE TEST FLOOD DIRECTLY TO THE NORMAL POOL RESERVOIR SURFACE YIELDS A TEST FLOOD ELEV. OF $128.3 + 1.9 = \underline{130.2}$. THE TOP OF THE DAM IS AT ELEVATION 132.3 AND, THEREFORE, IT IS EXTREMELY UNLIKELY THAT THE EMBANKMENT WOULD EVER BE OVERTOPPED.

AREA & STORAGE

ELEV.	AREA (AC)		
114.3 (BOTTOM)	68.4	TOP OF DAM	1273 AF
128.3 (NORMAL POOL)	73	TEST FLOOD	1120 AF
132.3 (TOP OF DAM)	73	(EL. 130.2)	

SECTION @ HAZARD AREA

1300' East of CHESTNUT HILL



.....
FLOOD HYDROGRAPH PACKAGE (HEC-1)
DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 20 FEB 79
.....

HYDRAULIC ANALYSIS OF CHESTNUT HILL RESERVOIR DAM

NATIONAL DAM SAFETY PROGRAM
NEW ENGLAND DIVISION COMPS OF ENGINEERS
10 0 0 0 0 0

[illegible]

-132.3 -1

134.3 139.3
15948-103600-

72	73
128.3	132.3

100

0.01 116.3
---HAZARD---

CHANNEL ROUTING

0.1	0.1
120	70

100-400

100

Year	Number of cases	Number of deaths	Number of cases per 100,000 population	Number of deaths per 100,000 population
1990	1,000	100	10.0	1.0
1991	1,100	110	11.0	1.1
1992	1,200	120	12.0	1.2
1993	1,300	130	13.0	1.3
1994	1,400	140	14.0	1.4
1995	1,500	150	15.0	1.5
1996	1,600	160	16.0	1.6
1997	1,700	170	17.0	1.7
1998	1,800	180	18.0	1.8
1999	1,900	190	19.0	1.9
2000	2,000	200	20.0	2.0
2001	2,100	210	21.0	2.1
2002	2,200	220	22.0	2.2
2003	2,300	230	23.0	2.3
2004	2,400	240	24.0	2.4
2005	2,500	250	25.0	2.5
2006	2,600	260	26.0	2.6
2007	2,700	270	27.0	2.7
2008	2,800	280	28.0	2.8
2009	2,900	290	29.0	2.9
2010	3,000	300	30.0	3.0
2011	3,100	310	31.0	3.1
2012	3,200	320	32.0	3.2
2013	3,300	330	33.0	3.3
2014	3,400	340	34.0	3.4
2015	3,500	350	35.0	3.5
2016	3,600	360	36.0	3.6
2017	3,700	370	37.0	3.7
2018	3,800	380	38.0	3.8
2019	3,900	390	39.0	3.9
2020	4,000	400	40.0	4.0

PREVIEW OF SEQU

ROUTE
ROUTE

END OF

100

1

OVERVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

ROUTE HYDROGRAPH TO
ROUTE HYDROGRAPH TO
END OF NETWORK

.....
 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79

RUN DATE 02/12/80
 TIME 10.18.57.

HYDROLOGIC ANALYSIS OF CHESTNUT HILL RESERVOIR DAM
 NATIONAL DAM SAFETY PROGRAM
 NEW ENGLAND DIVISION CORPS OF ENGINEERS

JOB SPECIFICATION
 NO 300 IDAY 10 NMIN 0 IMIN 0 METC 0 IPLI 0 IPRI NSTAN 0
 JUPEN 5 NWT 0 LROPT THACE 0

MULTI-PLAN ANALYSES TO BE PERFORMED
 PLAN=1 NPLAN=1

NO INFLOW → RTIOS= 0.00

HYDROGRAPH ROUTING

HYDROGRAPH ROUTING CHESTNUT HILL RES. DAM

ISTAU	ICOMP	IECON	ITAPE	JPLT	JHMT	INAME	ISTAGE	IAUTO
CHESN	1	0	0	0	0	1	0	0

ROUTING DATA
 ULOSS 0.00 CLUSS 0.00 AVG 0.00 IUES ISAME IOPT IPMP LSTR
 NSTPS NSTDL LAG AMSKK X TSK STORA ISPHAT
 1 0 0 0.000 0.000 0.000 132.

STAGE - DISCHARGE DATA

STAGE	132.30	134.30	139.30
FLOW	0.00	15648.00	103600.00

STAGE - STORAGE DATA

CAPACITY	0.	983.	1273.
ELEVATION	114.	128.	132.

SPILLWAY CREST ELEVATION → 132.3
 CHEL SPW10 CUNW ERPW ELEV ECUOL CANEA EXPL
 132.3 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA

TOP OF DAM ELEVATION → 132.3
 TOPEL COUD EXPI DAMWID
 132.3 0.0 0.0 0.

DAM BREACH DATA

HHWID 200.
 Z ELHM TFALL
 01 116.30 1.00 130.20

WSEL FAILED } BREACH DATA - FAILURE BEGINS
 130.20 130.20 } IMMEDIATELY WITH RESERVOIR
 SURFACE AT TEST FLOOD ELEVATION

BEGIN DAM FAILURE AT 0.00 HOURS

PEAK OUTFLOW IS 11111 AT TIME 1.00 HOURS

→ PEAK BREACH DISCHARGE

HYDROGRAPH ROUTING

CHANNEL ROUTING TO HAZARD CENTER

ISLAG	ICOMP	IFCON	ITYPE	JPLT	JPRI	INAME	ISAGE	IAUTO
HAZARD	1	0	0	0	0	1	0	0
ROUTING DATA								
GLUSS	0.0	0.000	AVG	IMFS	ISAME	ISPR	ESTR	0
0.0	0.000	0.00	1	1	0	0	0	0
NSIPS	1	0	LAG	AMSAK	A	TSK	STORA	ISPRAT
1	0	0	0.000	0.000	0.000	-1.	0	0

NORMAL DEPTH CHANNEL ROUTING

UN(1)	UN(2)	UN(3)	ELNVT	FLMAX	MLNTH	SET
.1000	.1000	.1000	99.0	120.0	1300.	.01200

FLOW AREA CHARACTERISTICS AT DAMAGE AREA

CROSS SECTION COORDINATES--STA+ELEV+STA+ELEV--FTC	370.00	49.00	340.00	99.00
0.00 120.00 70.00 110.00 320.00 100.00				
440.00 100.00 440.00 110.00 520.00 120.00				

CROSS-SECTION OF FLOW AREA AT DAMAGE CENTER

STORAGE	0.00	2.47	7.06	12.70	19.41	27.16	35.98	45.86	56.79	68.77
OUTFLOW	81.82	95.56	109.71	124.25	139.20	154.55	170.30	186.45	203.00	219.95
STAGE	17084.32	21431.61	26247.51	31525.74	37262.43	43455.46	50104.03	57208.36	64769.43	72788.90
FLOW	99.00	100.11	101.21	102.32	103.42	104.53	105.63	106.74	107.84	108.95
	110.05	111.16	112.26	113.37	114.47	115.58	116.68	117.79	118.89	120.00
	0.00	105.20	543.41	1293.90	2372.49	3801.80	5606.25	7810.68	10439.40	13514.02
	17084.32	21431.61	26247.51	31525.74	37262.43	43455.46	50104.03	57208.36	64769.43	72788.90

MAXIMUM STAGE IS 108.2

WATER ELEVATION AT DAMAGE AREA

**CHESTNUT HILL RESERVOIR DAM -
BREACH ROUTED TO DAMAGE CENTER**

SUMMARY OF DAM SAFETY ANALYSIS

INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
130.20	132.30	132.30
1120.	1273.	1273.
0.	0.	0.

PLAN 1	ELEVATION	STORAGE	OUTFLOW
0.00	130.20	1120.	0.

MAXIMUM OF PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.00	0.00	1120.	11814.	0.00	1.00	0.00

TEST FLOOD ELEVATION
PLAN 1 STATION HAZARD

NATL	FLOW	MAXIMUM STAGE-FT	TIME HOURS
0.00	11526.	108.2	1.00

ROUTED OUTFLOW
FLOW THROUGH DAMAGE AREA
FLOW ELEVATION AT DAMAGE AREA

6.1

APPENDIX E

INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

NOT AVAILABLE AT THIS TIME

END

FILMED

7-85

DTIC